BACK IN THE WORKSHOP: 03/07/24



Yep! It's broken. Rex's verdict on viewing the table for the first time in all its glory? It's knackered. He began the work ...



Cut new piece of metal.




Attach new piece.



Drill holes



.... and weld. All very much as before.



There was a loose pivot on the latching bar ... ??!







The solution – grind off the original welds and remove the whole leg assembly to get access to the pivot pin. Then weld the pin in place.





Next - Four of the 12 L shaped brackets that hold the top to the frame had been torn out.



Sigh! Drill out old rivet. Hit bracket with a hammer. Glue some wood to the frame. Attach newly flattened bracket to wood and to frame





Some extra assistance from Pebbles

SORTED!
One down

Ta Rex.